



SIL RS-92

Service Information Letter - Fuel Systems

SMALL RECIPROCATING ENGINES

RSA-10ED1

11/5/08

Page 1 of 1

SUBJECT: CLARIFICATION OF IDLE LEVER STEM MARKING ON SERVO PARTS LIST 2524500-9

PURPOSE: To provide correction of idle lever stem marking

- A. EFFECTIVITY: This Service Information Letter is applicable to all RSA-10ED1 fuel injection servos, parts list 2524500-9. These servos are installed on Lycoming L/TIO-540-J2BD/J2B engines.
- B. DESCRIPTION: Original marking on part number 2537856 idle lever stem is “AK” with a revision letter “E”. On new production idle lever stems the revision number has been removed. These now have the “AK” marking only.

1. Reference manual 15-458G Change 1, IPL, Figure 3

Item Number	Part Number	Description
160C	2537856	Stem, Idle valve (Code “AK”)

Note: Manual 15-458G Change 1, IPL, Figure 3 identification code for this idle lever stem is incorrectly identified as “E”.